MOSQUITO CREEK LAKE STILLING BASIN CONCRETE REPAIRS **US Army Corps of Engineers BUILDING STRONG®**

MOSQUITO CREEK LAKE





Outlet Works Stilling Basin






Stilling Basin Training Walls





1949 Expansion





1949 Construction





Non-Shrink Polyurethane Water Cut-Off Foam Seal Grout








Two-Part, Water-Activated, Hydrophobic, Semi-Rigid






Cofferdam Construction






Drilling Ports and Inserting Mechanical Packers






Injecting Grout





Injection Ports on Low Wall





Injection Ports Patched



